

DEPARTMENT of ENVIRONMENT and NATURAL RESOURCES Minerals & Mining Program - Oil & Gas Section 2050 West Main, Suite #1, Rapid City, SD 57702-2493 Telephone: 605-394-2229, FAX: 605-394-5317 FORM 2

APPLICATION FOR PERMIT TO DRILL

Well Name and Number	and longitude (if
Rapid City, SD 57701 Name and Address of Drilling Contractor and Rig Number: Elenburg Exploration, Inc. Rig 10 P. O. Box 2440, Casper, WY Surface Location of well: Qtr-Qtr, Sec, Twp. Rge, County, feet from nearest lines of section, and latitude available): SE NE Sec 18 T16N R2E, Harding County, SD 1475 FNL 1310 FEL Lat 45 deg 21' 12.90" Lon 103 deg 55' 16.73" If Directional, top of pay and bottom hole location from nearest lines of section: Straight Hole Acres in Spacing (Drilling) Unit 598.48 Description of Space Section 18:Lots 1-4, E Well Name and Number Elevation Field and Pool, or Wildcat Proposed	and longitude (if
Surface Location of well: Qtr-Qtr, Sec, Twp, Rge, County, feet from nearest lines of section, and latitude available): SE NE Sec 18 T16N R2E, Harding County, SD 1475 FNL 1310 FEL Lat 45 deg 21' 12.90" Lon 103 deg 55' 16.73" //So fur f Directional, top of pay and bottom hole location from nearest lines of section: Straight Hole Acres in Spacing (Drilling) Unit 598.48 Description of Space Section 18:Lots 1-4, E Well Name and Number Elevation Field and Pool, or Wildcat Proposed	
Well Name and Number	/2W/2, E/2
Heikkila #5-18 3470.8 Wildcat 3850	Depth and Formation
	Dakota
Size of Hole Size of Casing Weight per Foot Depth Cementing Program (amount, typ 10 12 1/4 8 5/8 5 1/2 15.5 3850 Good Sx 50/50 PozMix w/1 15.5 Cementing Program (amount, typ 225 Sx G with 2% CaCl 600 Sx 50/50 PozMix w/1 600 Sx 50/50 PozMix w/1	Fluid Loss Additi
Describe Proposed Operations (Clearly State all Pertinent Details, and Give Pertinent Dates, Including Proposed Work). Use additional page(s) if appropriate. Spud well approximate Drill 12 1/4 in hole to 400 ft. Run and cement 8 5/8 in casing at Install and test BOP. Drill out with 7 7/8 in bit, drill to 3850 Log and test as needed. If productive run and cement 5 1/2 in cas productive, plug and abandon lower hole, run 4 1/2 in casing to 75 complete as Shannon gas well.	400 ft. ft. ing, if non
I hereby certify that the foregoing as to any work or operation performed is a true and correspond of Lynn Moser Signature Lynn Moser Name (Print) WESTERN FIEL	CAL S'IRYEY18/03
FOR OFFICE USE ONLY	